

## Product Change Notification

**MultiConnect<sup>®</sup> eCell (MTE and MTE2)**  
**MultiConnect<sup>®</sup> rCell 500 Series (MTR5)**  
**MultiConnect<sup>®</sup> rCell 600 Series (MTR6)**  
**MultiConnect<sup>®</sup> CBRS Wi-Fi AP (MTCAPW)**

## Updated Firmware Available

Date: April 6, 2022

### Product Change Notification (PCN) Number

PCN 04062022-001 (Firmware Update)

### Overview

In June 2022, an updated firmware version will be available to resolve [CVE-2022-0778](#) and other openssl CVE ([openssl release notes](#))

- See [part numbers impacted](#) for details

### Suggested Action Plan

#### Customers

1. Recognize that impacted devices require a firmware update to resolve a security vulnerability
2. Evaluate the new firmware version and update deployed devices if needed
3. Additional information
  - Technical inquiries: [support.multitech.com](mailto:support.multitech.com)
  - Sales inquiries: email [sales@multitech.com](mailto:sales@multitech.com)

#### Distributors

- Forward this announcement to others in your organization who are actively involved in the sale or support of access points, routers, and Ethernet bridges
- Encourage customers to evaluate the new firmware version in their environment.

### CONTENTS

[Overview](#)

[Suggested Action Plan](#)

[Firmware Overview](#)

[Schedule](#)

[Model Numbers](#)

[Upgrade Process](#)

[Additional Information](#)

## Firmware Overview

New firmware versions include the following operating system component update

<p>Updated OpenSSL</p> <ul style="list-style-type: none"> <li>• OpenSSL updated to version 1.1.1n</li> <li>• Resolution to <a href="#">CVE-2022-0778</a> and other openssl CVE (<a href="#">openssl release notes</a>)</li> <li>• Additional information available at: <a href="http://www.multitech.com/landing-pages/security">http://www.multitech.com/landing-pages/security</a></li> </ul>	-
---	---

## Schedule

New firmware versions will be available for download in June 2022.

## Ordering Part Numbers Impacted

The following ordering part numbers are impacted by these updates:

- MultiConnect® eCell
  - MTE-LAT6-B07-US
  - MTE-LEU6-B07-EU-GB-AU
  - MTE2-L12G2-B07-US
- MultiConnect® rCell 500 Series
  - MTR5-LEU2-B04.R1-EU-GB
- MultiConnect® rCell 600 Series
  - MTR6-L12G1-B04-US
- MultiConnect® CBRS Wi-Fi AP
  - MTCAPW-L12G2-A600VA-CUA

## Upgrade Process

Updated firmware is available at [www.multitech.com](http://www.multitech.com).

1. Select the category and product family of interest
  2. Locate and select the correct model number from the Product Listing
  3. Visit the DOWNLOADS tab for the list of available firmware downloads
- MultiConnect® eCell
    - MTE-LAT6-B07-US <https://www.multitech.com/models/92507165LF>
      - DOWNLOADS tab, MTE-LAT6-v211
    - MTE-LEU6-B07-EU-GB-AU <https://www.multitech.com/models/92507166LF>
      - DOWNLOADS tab, MTE-LEU6-v211
    - MTE2-L12G2-B07-US <https://www.multitech.com/models/92507163LF>
      - DOWNLOADS tab, MTE-Lxxx-v308
  - MultiConnect® rCell 500 Series
    - MTR5-LEU2-B04.R1-EU-GB <https://www.multitech.com/models/92507337LF>
      - DOWNLOADS tab, MTR5-LEU2-v420
  - MultiConnect® rCell 600 Series
    - MTR6-L12G1-B04-US <https://www.multitech.com/models/92507338LF>
      - DOWNLOADS tab, MTR6-L12G1-v506
  - MultiConnect® CBRS Wi-Fi AP
    - MTCAPW-L12G2-A600VA-CUA - <https://www.multitech.com/models/92507151LF>
      - DOWNLOADS tab, MTCAPW-L12G2-v405

### **Additional Information**

If you have any questions regarding this Product Change Notification, please contact your MultiTech sales representative or visit the technical resources listed below:

#### **World Headquarters – USA**

+1 (763) 785-3500 | [sales@multitech.com](mailto:sales@multitech.com)

#### **EMEA Headquarters – UK**

+(44) 118 959 7774 | [sales@multitech.co.uk](mailto:sales@multitech.co.uk)

#### **MultiTech Security Advisories**

[www.multitech.com/landing-pages/security](http://www.multitech.com/landing-pages/security)

MultiTech monitors industry news and announcements to identify security issues that may impact our devices and operating systems and strive to provide the information and tools to keep your deployments secure and online.

#### **MultiTech Developer Resources:**

[www.multitech.net](http://www.multitech.net)

An open environment where you can ask development related questions and hear back from MultiTech engineering or a member of this community.

#### **Knowledge Base:**

<http://www.multitech.com/kb.go>

Immediate access to support information and resolutions for all MultiTech products.

#### **MultiTech Support Portal:**

[support.multitech.com](http://support.multitech.com)

Create an account and submit a support case directly to our technical support team.

#### **MultiTech Website:**

[www.multitech.com](http://www.multitech.com)

#### **Trademarks and Registered Trademarks**

MultiConnect, MultiTech and the MultiTech logo are registered trademarks of Multi-Tech Systems, Inc. All other trademarks or registered trademarks are the property of their respective owners.

Copyright © 2022 by Multi-Tech Systems, Inc. All rights reserved.

**ATTACHMENT I**  
**Identifying Firmware Version**

When logging into the device via the user interface, the user can easily identify the version of firmware on their device.



Firmware version 405  
MTCAPW-L12G2-v405

**Revision History**

Version	Author	Date	Change Description
-001	DT	04/04/2022	Original version